


1/20












4/20




5/20



6/20




7/20




8/20


FIG.8









10/20




OBLON, SPIVAK, ET AL DOCKET #: 248499US8 INV: Toshihiro SUZUKI, et al. SHEET 11 OF 20



12/20



13/20




14/20

FIG.14


ROUTING TABLE (NETWORK MANAGEMENT SERVER NCPF)

HoA	RA#1	RA#2
3.3	c.1	_
1.1	a.1	_
2.2	b.3	d.3
4.4	b.2	d.2
5.5	b.1	d.1
	:	:


OBLON, SPIVAK, ET AL DOCKET #: 248499US8 INV: Toshihiro SUZUKI, et al. SHEET 15 OF 20




16/20




OBLON, SPIVAK, ET AL DOCKET #: 248499US8 INV: Toshihiro SUZUKI, et al. SHEET 17 OF 20



18/20





20/20

